

Fiber splicing in a Finnish fiber fusion machine



Overview

Fusion splicing of fibers is a technique of making low-loss fiber joints by fusing fiber endfaces together. It is widely used in fiber optics.

Key Takeaways

Fiber splicing in a Finnish fusion splicer, such as the APS FX35, uses precise core-to-core alignment and controlled heat to create low-loss, permanent fiber connections. Overview of Fusion Splicing

Fusion splicing is a process that permanently joins two optical fiber ends by melting them together with an electric arc, creating a continuous glass path that minimizes signal loss and back reflectance. Unlike mechanical splicing, which relies on sleeves and gels, fusion splicing produces a strong, durable joint suitable for long-term telecommunications networks. Typical splice loss is very low, often below 0.05 dB when performed correctly.

APS FX35 Features

The APS FX35, a Finnish fiber fusion splicer, is designed for FTTx applications and supports various fiber types, including 250µm, 900µm, flat cables, and fiber jumpers. Key features include:

- Core-to-core alignment system for ultra-low splicing loss
- AUTO splicing mode with real-time fiber core display
- Integrated heating for protective sleeves, completing in about 25 seconds

- Battery life supporting up to 330 splicing and heating cycles
- Fiber identification to ensure correct fiber type and orientation These features make the FX35 suitable for both field installations and controlled environments, providing consistent, high-quality splices .

Splicing Procedure

- Prepare the fibers: Strip the protective coating to expose the bare glass, then clean and cleave the fiber ends with a precision cleaver. A clean, sharp cleave is critical to minimize splice loss .
- Load fibers into the splicer: Place the fibers into the V-grooves or holders. The FX35 uses a camera system to align the fiber cores automatically .
- Splice the fibers: The machine generates an electric arc to melt the fiber tips and fuse them together. Core alignment ensures minimal signal loss .
- Protect the splice: Apply a heat-shrink sleeve over the splice point. The FX35 heats the sleeve to create a secure, sealed barrier against moisture and mechanical stress .
- Inspect the splice: The splicer estimates optical loss and indicates if a splice needs to be redone. Visual inspection can confirm proper alignment and absence of defects .

Best Practices

- Always use the manufacturer-recommended cleaver and follow the FX35 manual for optimal settings .
- Keep fibers free from dust and debris during preparation and splicing .
- For fibers with special coatings or large cores, repeat the ARC step if minor defects appear, but avoid more than two attempts .
- Regularly calibrate the splicer and clean electrodes to maintain consistent performance . Using these procedures, the APS FX35 can achieve reliable, low-loss splices suitable for FTTx, FTTH, and other high-performance optical networks .

Article Content

Fusion Splicing of Fibers – electric discharge, fusion splicers

Fusion splicing of fibers is a technique of making low-loss fiber joints by fusing fiber endfaces together. It is widely used in fiber optics.

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: <https://alfa-pro.co.za>

Technical inquiry: <https://alfa-pro.co.za/contact.html>

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

